

Kairos Support Information(動作確認結果)

1. Confirmed product (対象機器)


Vender	Product	Firmware Version
H3C	S9850-32H	7.1.070, Release 6635
H3C	S6850-56HF	7.1.070, Release 6616P01

2. Test Environment(動作確認環境)

Equipment (使用機器)

Equipment	Model	S/W Version	Remarks
Kairos Core server	AT-KC1000	Ver. 1.7.3	
	AT-KC200	Ver. 1.7.3	
Kairos Creator	AT-SFC10	Ver. 1.7.3	Windows 11

Test System Diagrams(構成図)



3. Test items & results(確認項目と結果)

3.1 Packet Error Check

SWITCH	Packet Error Check
S9850-32H(Spine-Amber)	OK (No Packet Error was found)
S9850-32H(Spine-Blue)	OK (No Packet Error was found)
S6850-56HF(Spine-Amber)	OK (No Packet Error was found)
S6850-56HF(Spine-Blue)	OK (No Packet Error was found)

3.2 IP Stream Test

Device	Locked to PTP	Stream Validation	
		Video (ST2110-20)	Audio (ST2110-30)
AT-KC200	OK	OK	OK
AT-KC1000	OK	OK	OK
AK-UCU700	OK	OK	OK
AW-UE160	OK	OK	OK
SNP	OK	OK	OK
NEURON	OK	OK	OK
LV5600	OK	OK	OK
PHABRIX	OK	OK	OK
PRISM	OK	OK	OK

The information in this document shows the test results under specific environment only. Actual behaviors and operations in each environment can be different and the same results are not guaranteed in all environments.

注意：掲載される動作環境情報はテスト実施時点での内容であり、すべての環境で動作を保証するものではありません。